
DATE REV COMMENTS

A INITIAL RELEASE


A1 A/R 780 MINOR DOC CHANGES

B MINOR CHANGES

COMPUTER CONTROLLED DRAWING DO NOT REVISE MANUALLY




CONNECTION TO OLDER RECEIVERS SUCH AS COLLINS 51R8, 51RV-1, KING KNR660 AND SIMILAR RECEIVERS. SEE NOTE 1.



United LXF10VB222M or equivalent.

## ARINC NAV RECEIVERS KNR634 AND COLLINS VIR-30A (FOR VIR-30M SEE ABOVE) SEE NOTE 2.



## NOTES:

- 1. THE SN3500 REQUIRES DC FLAG SIGNALS. SOME VERY OLD RECEIVER DESIGNS OUTPUT UNSMOOTHED DC DUE TO A LACK OF FILTERING CAPACITORS. THE SN3500 WILL SHOW UNSTABLE FLAG OPERATION UNLESS SMOOTHING CAPACITORS ARE ADDED AS SHOWN. THE CAPACITORS CAN BE MOUNTED ON A TERMINAL BLOCK NEAR THE RECEIVERS. CONSULT THE RECEIVER SERVICE MANUAL SCHEMATICS AS REQUIRED.
- 2. FOR ARINC NAV RECEIVER USING 400HZ DIFFERENTIAL RESOLVER:
- a) THE NAV RCVR AND SN3500 MUST BE ON THE SAME INVERTER.
  b) ON OBS/RELAY/CDI MAINTENANCE PAGE SET OBS TYPE TO

