



by Honeywell

HOME	HISTORY	PRODUCTS & SERVICES	SUPPORT	NEWS & EVENTS	CONTACT US	MY ACCOUNT	
Product Catalogs	Data Link Weather	Database Downloads	Ordering	AV80R™			

Bendix/King by Honeywell



Software Update

AV80R™



AV80R Software/Firmware Update

[Download Handheld Update](#)
[Download ACE Update](#)

Other GPS Units

KLN 90/A/B, KLN 900, KLN 89/B, KLX 135A, KLN 35A, KLX 100 and KLN 94 GPS units

Our GPS Database Loader program makes updating navigation databases in KLN 90/A/B, KLN 900, KLN 89/B, KLX 135A, KLN 35A, KLX 100 and KLN 94 GPS units simple. The database loader program will use updates downloaded from Honeywell to update a GPS.

Users are strongly encouraged to read the requirements and instructions, which are available [here](#) as an Adobe PDF document.

[Click here](#) to download the Windows-compatible GPS Database Loader.
(Approximate size: 1.7 MB)

Windows VISTA compatible GPS Database Loader [Click here](#).
(Approximate size: 1.7 MB)

Windows VISTA compatible Alternate GPS Database Loader [Click here](#).
[Readme.txt](#) (Approximate size: 1.7 MB)

If a user has a SanDisk ImageMate SDDR-31 and wants to use ImageMate to update KLN 94 database cards, it is necessary to upgrade the firmware in ImageMate. A Windows 98 or Windows ME computer is required to upgrade the firmware in ImageMate. [Click here](#) to download the SDDR-31 firmware upgrade. If a user does not have a Windows 98/ME computer, they can send the ImageMate SDDR-31 to us and we can upgrade the firmware. Please [contact us](#) to do so.

Sign In Help

Honeywell ID:

Password:

[Forgot Password?](#)

Remember my ID on this computer

Forgot Honeywell ID? [Lookup](#)

Don't have Honeywell ID? [Register](#)

[Honeywell ID Management](#)

Learn More about AV80R Features

Visit [AV80R Microsite](#)
Visit [AV80R 3D Microsite](#)

Customer Support

Call Us
1-800-601-3099

[Contact Us](#)
[Warranty Info](#)

Sales & Service Locator

Airport Code
OR
Select Country Select State

[Advanced Search](#)