

SOCATA PART NUMBER	ATA	EQUIPMENT AND UPPER ASSEMBLY(IES)	TIME LIMIT	OPERATING LIMIT	REMARKS
TB20 61031000 TB20 61031001 TB20 61031911 TB20 61213000 TB20 61213911 Z00.N6069557227 Z00.N6069557228 Z00.N6069557229 Z00.N6069557237	32	PRESTOLITE landing gear electrohydraulic generator HYC 5005-12V HYC 5112-12V HYH5001-24V HYH5003-24V		2000 hrs	Contact SOCATA
TB20 61263000 TB20 61263001 TB20 61263002 TB20 61263911	32	LHC landing gear electrohydraulic generator	Replacement of seals 5 years	Overhaul 7500 hrs / 15 years	Contact SOCATA
Z00.N7886018400 Z00.N7886527861	32	Landing gear emergency valve GERDES A115-4 LEBOZEC 978D6-1	Replacement of seals 3 years		Contact SOCATA NOTE : Replace simultaneously with landing gear hydraulic fluid.
	34	VFR equipment		Calibration Refer to remarks	Must be performed by an approved radio center in compliance with the regulation in force in the country of use. (Examples : - FAR Part 91.411 and 91.413 : 24 months, - GSAC Instruction bulletin P-41-15, Ed. 1 dated September 2000 : . operational test plus flight check every 4 years maximum, . check on test bench every 6 years for equipment with French type approval prior to January 1, 1980 - refer to GSAC Instruction bulletin P-04-30.).